



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE0057/1

Work Order Type: Weatherization

Audit Name: Audit DE0057

CLIENT INFORMATION

Client Name:

Address:

Client ID: Client 50005DE0057

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE

Agency Phone: (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH
COVINGTON, TN 38019

Fax: (901) 476-5258

Email Address: gloria.v.williams@tn.gov

Agency Contact: Treadwell, Dwight

Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: Client 50005DE0057

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0057/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 5

Measures

Measure 1 Infiltration Redctn			Components				Inspected		
Comment							<input type="checkbox"/>		
1. Patch hole in front of bathroom on the mobile home side									
2. Caulk front door									
3. Glaze window # 8									
4. Weatherstrip Back door									
5. Threshold back door									
6. Block and Seal W3, W11									
7 Caulk W9, W10 - (Windows have storms and bars - that might have to be removed to do Air infiltration work)									
8. Patch hole in the wall behind bath tub on addition side									
9. Air seal plumbing penetrations - kitchen - bathroom - laundry									
			Estimated				Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>			<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>			<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Measure 2 DWH Tank Insulation			Components				Inspected		
Comment							<input type="checkbox"/>		
			Estimated				Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>			<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>			<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Client Name:

Client ID: Client 50005DE0057

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0057/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 5

Measure 3 DWH Pipe Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 4 Replace A/C				Components window units				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Cooling Equipment	Window A/C -	Each	1					
2	Labor	Window A/C -	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 5 Replace Htg. System**Components** 50,000 BTU wall HT**Inspected****Comment** Allow for 10 feet of gas line and

Recommend - ADD (1) Double 50,000 BTU vented wall heater

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Space Heater - 20 kBtu/h NG Existing, 46 - 65 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Space Heater - 20 kBtu/h NG Existing, 46 - 65 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 CO Monitor is Needed****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: Client 50005DE0057

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0057/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 5

**Measure 7 Fix Water Leaks Present (Attic) -
Evaluate replacing roof****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 Install Kitchen Exhaust Fan****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Kitchen exhaust fan	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: Client 50005DE0057

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0057/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 5